





















Site Information	Depth (in)	Aliquot 1		Aliquot 2		Aliquot 3		Aliquot 4		Aliquot 5	
Site: 35 th Avenue Superfund Site Contract: EP-S4-15-01 TDD: 0002/OT-02-002 OSCs: Rick Jardine Property ID: CV0341B Date: March 11, 2015 Times: 6" 13:07 12" 13:17 18" 13:20 24" 13:25 Photographer: Nairimer Berrios-Cartagena Official Photograph Set No.: 1 Hang auger soil description by interval and related pictures for sample location CV0341B.	0	0-4" Dark brown silt. 4-6" gravel with silt, light brown		Orange brown silt w/ glass.		Dark brown silt.		Dark brown silt w/ tan, silty clay		Brown silt w/ gravel.	
	6			Refusal at 6"							
		Brown/tan clay w/ traces of silt.		Refusal at 6"		6-8" crushed slag and gravel.		Dark brown/tan gravely, silty clay.		Dark brown/tan gravely, silty clay.	
	12					8-12" Brown/tan silt.					
		Tan, wet clay.		Refusal at 6".		Tan clay, damp.		Brown clay, wet.		Tan clay, wet.	
								Refusal at 14"			
	18										
		No aliquot due to water table.		Refusal at 6".		Yellow clay, stiff.		Refusal at 14"		Refusal at 20"	
	24										